Printed on: 2/29/2012 4:06:34 PM

National Transportation Safety Board			NTSB ID: CEN12FA161				Most Critical Injury: Fatal			
			Occur	rence Date: 02/19		Investigated By: NTSB				
AVIATION Occ			Occur	Occurrence Type: Accident						
Location/Time										
Nearest City/Place State				Zip Code	Local Time)	Time Zone			
Hayden CO			81639	1530		MST				
Aircraft Information										
Registration Number	Aircraft Manu	Aircraft Manufacturer					Model/Series Number			
N4772A	CESSNA 414A									
Type of Aircraft: Airplane			Amateur Built Aircraft? No							
Injury Summary:	Fatal	2		Serious	4	Minor			None	
Revenue Sightseeing Flight: No				Air Medical Transport Flight: No						

Narrative

Brief narrative statement of facts, conditions and circumstances pertinent to the accident/incident:

On February 19, 2012, approximately 1530 mountain standard time, a Cessna 414A, N4772A, impacted terrain while attempting to land at the Yampa Valley Airport (KHDN), Hayden, Colorado. The commercial pilot and one passenger were fatally injured and four passengers were seriously injured. The airplane was substantially damaged. The airplane was registered to and operated by a private individual and operated as a personal flight under the provisions of 14 Code of Federal Regulations Part 91. Instrument meteorological conditions developed for the flight, that operated on an instrument flight rules (IFR) flight plan. The flight departed the Dalhart Municipal Airport (KDHT), Dalhart, Texas, approximately 1415 central standard time.

An initial review of air traffic control information revealed that the pilot was cleared by air traffic control to the initial approach fix (REVME) for the instrument landing system (ILS) approach for runway 10.

Airfield personnel provided an enhanced UNICOM service for inbound traffic and were monitoring UNICOM and Denver Center at the time of the accident. Airfield personal heard the pilot report he was on final approach over the UNICOM frequency. Airport personnel then selected the airport lights to high, and the pilot acknowledged the light status. There was no report of a distress call being made by the pilot prior to the accident.

In an interview with the airplane's owner, who was also a passenger, he stated the airplane was maneuvering to land at KDHN. The pilot had made two left turning circles and had begun a third circle when the he perceived that the airplane "just stalled." He added the airplane fell straight down and impacted terrain. In addition, he commented that the engines were running at the time of the accident.

The accident site was located about 95 yards south-southwest from the edge of runway 10. The wreckage path was aligned generally along a 090 heading. The debris path contained the left aileron and right propeller. The main wreckage came to rest facing a 320 heading. The fuselage displayed buckling and crushing throughout its length. All major airplane components were accounted for at the accident site.

At 1515, an automated weather reporting facility located at KHDN reported winds from 310 at 8 knots, 5 miles visibility, few clouds at 800 feet, scattered clouds at 1,700 feet, broken ceiling at 2,900 feet, temperature -1 Celsius (C), dew point -3 C. At 1535, winds were reported from 290 at 10 knots gusting to 14 knots, visibility 1/4 mile, ceiling overcast at 400 feet, temperature -2 C, dew point -3 C. This facility does not report precipitation.

Updated on Feb 27 2012 9:14AM

TRANSO
National Transportation Safety Board
0 7
PRELIMINARY REPORT
7 3
AVIATION

NTSB ID: CEN12FA161

PRELIMINARY REPORT			Occurrence Date: 02/19/2012										
AYIATION		Occurrence Type: Accident]						
Other A	ircraft Involved												
Registrati	egistration Number Aircraft Manufacturer							Model/Series Number					
Accider	nt Information	•						•					
Aircraft Damage: Substantial Accide						Occurred Durin	ng:						
Crew	N	ame				Certificate No.				Injury			
Pilot	On File												
2													
3	3												
4													
5													
6													
Operator Information													
Name Operator D HUMPAL SCOTT A						nator Code		Doing Busine	ess As				
Street Address City WC						SBORO		State Zip Code TX 78393-0637					
-Type of Certificate(s) Held: None													
Air Carri	er Operating Certificate	s):											
Operating Certificate:						Operator Certificate:							
Regulation Flight Conducted Under: Part 91: General Aviation													
Type of F	light Operations Conduc	ted: Personal											
Flight F	Plan/Itinerary												
Type of Flight Plan Filed: IFR													
Last Departure Point						State	Airport	t Identifier					
Dalhart						TX	DHT						
Destination						State	Airport	Identifier					
Same as Accident/Incident Location							HDN						
Weathe	er Information												
Investigator's Source: Unknown						Facility ID: HDN Observation Time (Local): 1535							
Sky/Lowest Cloud Condition: Thin Overcast						400 Ft. /	AGL						
Lowest C	Lowest Ceiling: Overcast 400 Ft. AGL					isibility:	0.25	SM	Altim	neter:	29.62	"Hg	
	PRELIMINARY INFORMATION - SUBJECT TO CHANGE Page 2												

National Transportation Safety Board PRELIMINARY REPORT

NTSB ID: CEN12FA161

Occurrence Date: 02/19/2012

I KELIMINAKI KEI OKI			000	Occurrence Date. 02/19/2012					
AVIATION				currence Ty					
Weather Information		(Continued from page 2	?)						
Temperature: -2	2°C	Dew Point:	-3 °C	Wind D	irection: 290				
Wind Speed: 10	Kts.	Gusts: 14	Kts.	Weathe	er Conditions at Accident S	nt Conditions			
Administration Data									
Notification From NW ROC						Date			
1444 1400									
FAA District Office/Coordinator					Investigator-In-Charge (IIC)				
FAA FSDO Tom Wiesner					Jason T. Aguilera				
					·				